11/30/2011 Product ID Ma 8100132	Departr anufacturei	ment: Rad		Service Ir	icident R	eport - Go	od Sama	ritan Me	edical (Center										
Product ID Ma	·	nent: Rad	liology			Service Incident Report - Good Samaritan Medical Center														
	anufactureı		11/30/2011 Department: Radiology																	
8100132		Model #	Serial #	Description	# of PM's	Limit of Liability														
	Philips	BV22	CHJ3656	C-ARM	2	\$75,400.00														
Claim # L	Loss Date	Туре	Normal Labor	Travel	OT Labor	Mileage	Parts	Shipping	Тах	Total Claim	Vendor	Invoice	Amount Paid	Date Paid						
081-4165016 12	1/20/2010	Repair	\$300.00	\$60.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$360.00	Philips	223992	\$360.00	12/27/2010						
Description of Re	epair: Repair,	oil spots	on image. Orde	ered optical o	oil for II/TV .	loint seal. Tigh	ntened II tub	e and rese	aled II to	TV Camera tu	bes.									
081-4311006 2 Description of Re		РМ	\$480.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$480.00	Philips	244019	\$480.00	3/25/2011						
Summary for ID 8 Total Paid: Percentages:	8100132		\$780.00 92.85%	\$60.00 7.14%	\$0.00 0.00%	\$0.00 0.00%	\$0.00 0.00%	\$0.00 0.00%	\$0.00 0.00%	\$840.00 100.00%										
						Limit of														
Product ID Ma	anufacture	Model #	Serial #	Description	# of PM's	Liability														
8100835	Philips	BV29	4522102	C-ARM	2	\$101,295.00														
Claim # L	Loss Date	Туре	Normal Labor	Travel	OT Labor	Mileage	Parts	Shipping	Тах	Total Claim	Vendor	Invoice	Amount Paid	Date Paid						
081-4126002	4/6/2010	Repair	\$540.00	\$60.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$600.00	Philips	218736	\$600.00	5/15/2010						
Description of Repair: Repair, Shutters are off center. Realigned near ring shetters and iris; small focal spot shifted with age.																				
	7/31/2010	Repair	\$120.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$120.00	Philips	228734	\$120.00	9/2/2010						
Description of Repair: Repair. Set screw lock is broken off. Need easy out to remove screw. Drilled out old screw and installed new one.																				
081-5025016 12	1/16/2010	Repair	\$480.00	\$60.00	\$0.00	\$0.00	\$1,572.61	\$0.00	\$0.00	\$2,112.61	Philips	247063	\$2,112.61	12/28/2010						
Description of Re	escription of Repair: Repair, replaced monitor and adjusted.																			
Summary for ID 8	8100135																			
Total Paid:			\$1,140.00	\$120.00	\$0.00	\$0.00	\$1,572.61	\$0.00	\$0.00	\$2,832.61										
Percentages:			40.24%	4.23%	0.00%	0.00%	55.51%	0.00%	0.00%	100.00%										